





SYSTEMS QMH1 Threaded Stud Assembly



Item	Cable	Threads	Hole to Drill
QMH 1-0603	1 / 8 "	1/4" - 20	0.28"
QMH 1-0605	3/16 "	1/4" - 20	0.40"
QMH 1-0603-HS	1 / 8 "	1/4" - 20	0.28"
QMH 1-0605-HS	3/16 "	1/4" - 20	0.28"
QMH 1-0805	3/16 "	5/16" - 18	0.38"
QMH 1-0806	1 / 4 "	5/16" - 18	0.50"
QMH 1-1005	3/16 "	3/8" - 16	0.38"
QMH 1-1006	1 / 4 "	3/8" - 16	0.50"
QMH 1-1306	1 / 4 "	1/2" - 13"	0.50"
QMH 1-1610	3 / 8 "	5/8" - 11	0.72"
QMH 1-2013	1 / 2 "	3/4" - 10	0.88"
QMH 1-2216	5 / 8 "	7 / 8 " - 9	1.13"


SYSTEM QMH2 Lifeline Stud & Dome Swage Assembly



Item	Cable	Threads	Hole to Drill
QMH 2-0603	1 / 8 "	1 / 4 "	0.25"
QMH 2-0605	3/16 "	1 / 4 "	0.32"
QMH 2-0806*	1 / 4 "	5/16"	0.44"
QMH 2-1006*	1 / 4 "	3 / 8 "	0.44"

* Use 7/32" die to swage


SYSTEM QMH3 Lifeline Stud & Stud Assembly



Item	Cable	Threads	Hole to Drill
QMH 3-0603	1 / 8 "	1 / 4 "	0.25"
QMH 3-0605	3/16 "	1 / 4 "	0.32"
QMH 3-0806*	1 / 4 "	5/16"	0.38"
QMH 3-1806*	1 / 4 "	5/16"	0.38"
QMH 3-1006*	1 / 4 "	3 / 8 "	0.38"

* Use 7/32" die to swage

SYSTEM QMH4 Internal Threaded Swage Stud Assembly



Item	Cable	Threads	Hole to Drill
QMH 4-03	1 / 8 "	1 / 4 "	0.32"
QMH 4-05	3/16 "	1 / 4 "	0.36"
QMH 4-06	1 / 4 "	5/16"	0.50"

SYSTEM QMH5 Invisi-Thread



Item	Cable	Threads	Hole to Drill
QMH 5-03	1 / 8"	1 / 4"	0.22"
QHM 5-05**	3/16"	1 / 4"	0.32"
QMH 5-06*	1 / 4"	5/16"	0.38"

This system will not show any threads after installation.

* Use 7/32" die to swage ** Use 5/32" die to swage

SYSTEM QMH6 Swage Jaw & Jaw/Stud Turnbuckle Assembly



Item	Cable	Threads	Jaw Opening	Jaw Clearance
QMH 6-0603	1 / 8"	1/4"-20	0.32"	0.35"
QMH 6-0605	3/16"	1/4"-20	0.32"	0.35"
⊕ QMH 6-0603-HS	1 / 8"	1/4"-20	0.28"	0.35"
⊕ QMH 6-0605-HS	3/16"	1/4"-20	0.31"	0.35"
QMH 6-0806	1 / 4"	5/16"-18	0.42"	0.42"

* Larger sizes also available

SYSTEM QMH7 Swage Toggle & Toggle/ Stud Turnbuckle Assembly



Item	Cable	Threads	Toggle Opening
QMH 7-0603	1 / 8"	1/4"-20	0.30"
QMH 7-0605	3/16"	1/4"-20	0.30"
⊕ QMH 7-0603-HS	1 / 8"	1/4"-20	0.18"
⊕ QMH 7-0605-HS	3/16"	1/4"-20	0.30"
QMH 7-0806	1 / 4"	5/16"-18	0.42"

* Larger sizes also available

SYSTEM QMH8 Swage Deck Toggle & Deck Toggle/ Stud Turnbuckle Assembly



Item	Cable	Threads	Hole for Screw	Dist.bwn Holes
QMH 8-0603	1 / 8"	1/4"	1.30"	0.25"
QMH 8-0605	3/16"	1/4"	1.30"	0.25"
⊕ QMH 8-0603-HS	1 / 8"	1/4"-20	1.30"	0.25"
⊕ QMH 8-0605-HS	3/16"	1/4"-20	1.30"	0.25"
QMH 8-0806	1 / 4"	5/16"	1.56"	0.32"

SYSTEM QMH9 Swage Stud & Threaded Rod Turnbuckle Assembly



Item	Cable	Threads	Body Length
QMH 9-0603	1 / 8 "	1 / 4 "-20	3-5/8 "
QMH 9-0605	3/16 "	1 / 4 "-20	3-5/8 "
⊙ QMH 9-0603-HS	1 / 8 "	1 / 4 "-20	3-5/8 "
⊙ QMH 9-0605-HS	3/16 "	1 / 4 "-20	3-5/8 "
QMH 9-0806	1 / 4 "	5/16 "-20	4-1/8 "

Large sizes also available

SYSTEM QMH10 Swage Stud & Swage Stud/Lag Stud Turnbuckle Assembly




Item	Cable	Threads	Body Length
QMH 10-0603	1 / 8 "	1 / 4 "-Lag	3-5/8 "
QMH 10-0605	3/16 "	1 / 4 "-Lag	3-5/8 "
⊙ QMH 10-0603-HS	1 / 8 "	1 / 4 "-Lag	3-5/8 "
⊙ QMH 10-0605-HS	3/16 "	1 / 4 "-Lag	3-5/8 "
QMH 10-0806	1 / 4 "	5/16 "-Lag	4-1/8 "

QMH11 Machine Fork Swage / Machine Fork & Swage Stud Turnbuckle Assembly



Item	Cable	Threads	Fork Opening	Fork Clearance
QMH 11-0603	1 / 8 "	1 / 4 "-20	5/16 "	0.38 "
QMH 11-0605	3/16 "	1 / 4 "-20	3 / 8 "	0.45 "
QMH 11-0806	1 / 4 "	5/16 "-18	15/32 "	0.50 "

SYSTEM QMH 12 SlimFit Assembly



Item	Cable	Fitting Length	Threads	Hole to Drill
QMH 12-03	1 / 8 "	2-1/2 "	8M	3/8 "
QMH 12-05	3/16 "	3 "	10M	1/2 "
QMH 12-06	1 / 4 "	3-1/2 "	12M	5/8 "

This system will be assembly at job site, therefore the hole on the middle posts can be drill to cable size, and holes for end posts should be drill as indicated above. For detail see page 21-22